

Wall Replacement



Basement Block Wall Replacement

Movement or bowing is a common issue with block walls in a basement. Ground movement, moisture, expansive soils and or large tree roots, can be the cause. When extreme damage has been done replacing the wall may be the best and only option!



8" x 8" x 16" Masonry Block

*Rod & Cored 32" on Center for Support.
This Strengthens the Wall.*

Not only is it more appealing to replace the damaged wall with a new one, but it also provides a stable foundation for the home, maintains the value of the home and was professionally installed by one of the most experienced Crews in the Des Moines, Omaha area!

Most walls are installed from the inside with minimal disturbance to the area surrounding the house. This means less mess!



515.278.6100 Des Moines, IA
877.DRY.DOGS

402.393.2110 Omaha, NE